

Accessibility Site Survey of Selected Items
For
Title 24 of the California Building Code



Center for Advanced Learning
4016 South Central Avenue
Los Angeles, CA 90011

Certificate of Occupancy: 6-New Construction

This report contains sample findings and is **NOT** intended to be a comprehensive site inspection and is **NOT** intended to be a complete report.

December 17, 2009



Parking

Access aisles are not a minimum of 60 inches wide

No wheel stops at accessible parking spaces

No compliant curb ramps



International Symbol of Accessibility (ISA)

The ISA measures greater than 36 inches by 36 inches



Parking

Surface has a slope greater than 2%



Path of Travel Protruding Object

The leading edge of the fire extinguisher is more than 4 inches from the wall and greater than 27 inches from the floor and protrudes into the primary path of travel



Drinking Fountain

The leading edge of the drinking fountain is more than 4 inches from the wall and greater than 27 inches from the floor and protrudes in the primary path of travel; at adult standards



Interior Stairs

Stairway protrudes into the primary path of travel by providing a hazardous height range less than 80 inches

No barrier under the freestanding stairway



Stairs

Nosings are abrupt
Striping not within 1" of tread



Ramps at Main Entrance

Handrails only on one side
No handrail extensions
Ramp slopes greater than 8.33%



Elevator

Non-compliant hardware



Door Latch Side Clearance

No 12" latch side clearance from the push side

Bottom 10 inches of door not smooth due to door stop



Restrooms

All student restrooms are adult standards